Serial No. 10/707,653 RESPONSE TO OFFICE ACTION DATED APRIL 18, 2007

AMENDMENTS TO THE DRAWINGS

Figure 1 has been amended to more clearly reflect appearance and function of the fuel distributor valve 48. A replacement sheet is attached hereto.